Leigh Ann Johnson E. Nichols Pl. BB

Inspection Date: 03/06/2020

Property: E Nichols PI, Centennial, CO 80112

Tenant: Jordan (970) @live.com

Exterior

Inspection Ready for Review





2 Bedroom, 2.5 Bathrooms. Located in Villas at Highland Park HOA community.



Garage





No items on walls, and no oil marks. Electrical panel box was open, all breakers were in the "On" position. City trash can stored in garage.







Lawn






HOA Community responsible for management of lawn. Landscaping looked kept, and front poor was clear and clean.







Exterior Debris

Observed


No exterior debris was observed.





Main Level

Floors








Walls





Minimal items hanging on wall. Paint looks fresh. Fireplace was clean, but tenant was not present during inspection to determine if used regularly or not.







Hallways/ Stairs



Carpet appeared to be recently vacuumed. No visible stains or wear present.







Kitchen

Floor





Light traction marks visible on floor, but was only dust. No damage was found of any type.



Appliances





Microwave, Stove, Dishwasher, Refrigerator belong to property and are all functioning properly and were very clean on appearance. Microwave oven was also present on countertop.












Plumbing











Cabinets





Cabinets were in great condition. No problems detected.



Countertops





Countertops were clean and in great condition. Minimal items located on countertops.



Bedroom 1 - Master (Upstairs To left From Stairs)

Floor





Carpeted throughout room. Was clean with no visible stains and appeared to be recently vacuumed.







Very minimal items located on walls. Walls were clean with no visible problems.







Door/Closet





Bedroom 2 - Guest (upstairs to right)

Floor

Carpet throughout room. Was clean with no visible stains and appeared to be recently vacuumed.















Very minimal items located on walls. Walls were clean with no visible problems.



Door/Closet





Closet was empty with what appeared to be its contents in front. Door was secured.



Bathroom 1 - Master

Floor





Tile throughout. No chips or damage found.



Plumbing





No leaks or water damage found on and around plumbing. Toilet was not running upon entering room. Flushed and stopped running appropriately.













Mildew





None. Separate shower and bathtub.







Bathroom 2 - Guest Bedroom

Floor

Tile throughout. No chips or damage found.



Plumbing





No leaks or water damage found on and around plumbing. Toilet was not running upon entering room. Flushed and stopped running appropriately.









Mildew

None.







Floor





Hardwood floors looked good and had no visible damage.



Walls





Minimal items located on walls. No damage visible.



Plumbing





No water damage or leaks detected near or around sink. Toilet was not running upon entering room. Flushed and stopped running appropriately.





Laundry

Washer / Dryer





located upstairs in hallway. Connections were secure with no leaks or water damage of any kind detected.









Room


Good, tile chipped around floor drain, appears to be older floor.























Evidence of Pets

Observations



None. No toys, food, water, leashes, beds or any other type of evidence was visible during inspection.

Evidence of Unauthorized Occupants

Observations





Mechanical

HVAC/HWH



